

Complete Comfort Washing Instructions

Recommended for

Complete Comfort™

No.	Process	Comments	Time	Water Level	Temperature
1.	Flush		2-3 Min.	High	49°C
2.	Break		5-10 Min.	High	60°C
3.	Rinse		2 Min.	High	49°C
4.	Rinse		2 Min.	High	Cold
5.	Drain		2 Min.	None	None

Additional Recommendations

1. Mats do not require drying
2. This wash formula does not require extensive mechanical action
3. Lay mats flat following removal from the washer
4. The main purpose of this formula is to dissolve grease residue by using hot water to emulsify oils & greases